

VIBRATING TEST REPORT


Report No	NTO

NTC-SR2505012

Applicant's name: MIC Optoelectronic CO., LTD

Address

2nd floor,Third Building, 97# AiNan Road,LongDong, BaoLong Street, LongGang District, Shenzhen, China



DONGGUAN NEW TESTING CENTRE CO., LTD



TEST REPORT							
Luminaires							
Part 1: General re	Part 1: General requirements and tests — Luminaire Vibration						
Report Reference No:	NTC-SR2505012						
Date of issue:	May.10, 2025						
Total number of pages:	6 Pages						
Testing Laboratory:	Dongguan New Testing Centre Co., Ltd.						
Address:	1F & 3F, No. 1 the 1st North Industry Road Songshan Lake Science & Technology Park Dongguan, People's Republic of China 523808						
Tested by (name + signature):	Jack Zhang						
Approved by (+ signature)	Neil Zhong						
Approved by (+ signature): Applicant's name:	MIC Optoelectronic CO., LTD						
Address	2nd floor,Third Building, 97# AiNan Road,LongDong, BaoLong Street, LongGang District, Shenzhen, China						
Manufacturer's name:	MIC Optoelectronic CO., LTD						
Address:	2nd floor,Third Building, 97# AiNan Road,LongDong, BaoLong Street, LongGang District, Shenzhen, China						
Standard :	IEC 60598-1:2020 4.20 Rough service luminaires – Vibration requirements IEC 60068-2-6:2007						
Test specification:							
Procedure deviation:	N/A						
Non-standard test method :	N/A						
Testitem description:	LED Street Light						
Trade mark :	MIC						
Model/Type :	MSL-F30,MSL-F50,MSL-F60,MSL-F80,MSL-F100,MSL-F120, MSL-F150,MSL-F180,MSL-F200,MSL-F240,MSL-F300						
Rating	100-277VAC, 50/60Hz, 150W, CCT 5000K						




Vibration	Test Fred	quency	Test Duration	Vibration Amplitude	Test result	
Model:MLL-L150-2						
After the test, the luminaire shall have no loosened parts which could impair the safety.						
The direction of vibration is in the most onerous direction and the severity is:						
The luminaire is fastened in its most onerous but normal position of installation to a vibrationgenerator.						
Compliance is checked by the following vibration test (as specified in IEC 60068-2-6).						
Rough service lu	uminaires shall	have adequa	te resistance to vibrat	ions.		
Vibration Test	General desc	ription :				
	Vibration	tester	EV320H080	2025-01-23	2026-01-22	
Equipment			SV-1010			
Test Vibration		tester	DC-3000-30/	2025-01-23	2026-01-22	
	Equipmer	nt Name	Equipment No.	Validity Period	Validity Period	
Humidity		1	50-75%			
Temper	rature			25°C		
			Festing environmer	nt		
General produc	tinformation:					
All tests were conducted exclusively on model MSL-F150.						
singlereprese	ntative model o	nly.		-		
All models with	nin this series sl	hare an ident	ical structure; therefor	re, testing was conducted	d on a	
Supplementary	•	•		·· · · · · · · · · · · · · · · · · · ·	¥	
	•			n approval of the testing	laboratory.	
-			e only to the object te	sted.		
Throughout this	report a point is	s used as the	decimal separator.			
General remark		·				
- test object doe			. ,			
- test object doe		-	. ,			
- test case does		e test obiect .	: N (N/A)			
Possible test case verdicts:						
Date (s) of perfo	ormance of tests	tests Apr. 30, 2025 to May.10, 2025				
Date of receipt of	of test item			Apr. 30, 2025		
Testing:						

Vibration Test Frequency		Test Duration	Vibration Amplitude	Test result	
X-axis	10 Hz, 55 Hz, 10 Hz	30 min	0,35 mm	Pass	
Y-axis	10 Hz, 55 Hz, 10 Hz	30 min	0,35 mm	Pass	
Z-axis	10 Hz, 55 Hz, 10 Hz	30 min	0,35 mm	Pass	



Setup Photo Test model:MSL-F150, Axis: Vibration (X-axis)






Conclusion after the test:


The sample was tested in the X-axis direction. no significant changes were found in the test sample. The fixture can light up and function after the vibration endurance testing. Test result: Pass



Report No.: NTC-SR2505012

Setup Photo Test model: MSL-F150, Axis: Vibration (Y-axis)






Conclusion after the test:

The sample was tested in the Y-axis direction. no significant changes were found in the test sample. The fixture can light up and function after the vibration endurance testing. Test result: Pass



Report No.: NTC-SR2505012

Setup Photo Test model:MSL-F150, Axis: Vibration (Z-axis)



Conclusion after the test:

The sample was tested in the Z-axis direction. no significant changes were found in the test sample. The fixture can light up and function after the vibration endurance testing. Test result: Pass



Product Sample



Picture 1: The overview (Model: MSL-F150)



Picture 2: The overview (Model: MSL-F150)

--End of report--